

Tree Impacts and Arborist Assessment

- Construction Impact Removal (Total 6)
- Poor Suitability for Preservation (Total 52)*

* On October 1, 2012, two trees (#41 & 42) slated for removal have been damaged by natural causes whereby their entire canopy snapped off and fell into the pathway above playground leaving only tall snags.

Note: Trees rated with poor suitability are in poor health and have significant defects in structure that cannot be addressed through pruning or other measures.

- Proposed New Trees (163)
- Existing Trees to Remain

#1-442 Tree Tag Number

N

30 0 30 60

1"=30'-0"

Updated 10.3.2012

NO.	DATE	DESCRIPTION	BY	APP.

TABLE OF REVISIONS
THIS DRAWING WAS LAST MODIFIED: 08/13/12 14:18, BY: ebillow

REFERENCE INFORMATION & FILE NO. OF SURVEYS

INFRASTRUCTURE DIVISION
DEPARTMENT OF PUBLIC WORKS
CITY AND COUNTY OF SAN FRANCISCO

DESIGNED:	DATE:
KP/KO/JF	05/12
DRAWN:	DATE:
ES	05/12
CHECKED:	DATE:

APPROVED

SECTION MANAGER DATE:

DEPUTY DIVISION MANAGER DATE:

DIVISION MANAGER DATE:

SCALE: 1"=30'-0"

SHEET OF SHEETS

OF

GLEN CANYON PARK IMPROVEMENTS

TREE PLANTING AND REMOVAL PLAN

CONTRACT NO.	3071V
DRAWING NO.	
FILE NO.	
REV. NO.	

Drawing Path: W:\3071V Glen Canyon Park\2_Design\Working_Drawings\EA\Sheets\3071V_L-1.0-1.4_DEMO.dwg, Layout: Measurement Units are English
Plot Time: Wed, 22 Aug 2012 - 9:30am

Xrefs: W:\3071V Glen Canyon Park\2_Design\Working_Drawings\EA\ADOC1_TBE.dwg
W:\3071V Glen Canyon Park\2_Design\Working_Drawings\EA\Base_Plans\GBA_2010-40 Glen Canyon Park (compilation).dwg
W:\3071V Glen Canyon Park\2_Design\Working_Drawings\EA\Base_Plans\3071V_L_EXIST.dwg